

## Appendix 27.1\_INT

### Test Report

Example – Test report Heidelberg

VERSION: JANUARY 2008, PAGE 1 OF 1



Heidelberger Druckmaschinen AG - Postbox 1360 - D-69154 Wiesloch

Wiesloch 06.12.2007  
 Our ref KELLNER  
 Direct dial 06222/821826  
 Fax 06222/82991826  
 E-mail CHRISTIAN.KELLNER@HEIDELBERG.COM

#### Location Wiesloch

Heidelberger  
 Druckmaschinen  
 Aktiengesellschaft  
**Procurement**

D-69159 Wiesloch  
 Germany

Visiting address:  
 Gutenbergstraße

**Test report no. 3934848**  
**Page 1/1**

#### Delivery data

Delivery note number : 80063731  
 Delivery note date : 29.11.2007  
 Quantity delivered : 1,00 PC  
 Order number : 5701117850  
 TANDEM goods receipt No. : 1326435  
 SAP material document : 5008658982

#### Master data

Item no. : DS.651.6818/  
 HTN no. : DS.651.6818/  
 Description : Connecting line USsens.St.ausr.60B818  
 Material :  
 Test desk : W610

#### We found the following defects in the parts delivered by you:

Characteristic/Target value/Tolerance	Actual value	Number of defective items	Acceptance code
Completeness and correct assembly Manufacturing code: 666 2395	Faulty characteristic Grommet is missing.	1	RL

Please send a written comment within the next six weeks.

Attachment: 3934848

Quantity in complaint	Acceptance code	Codes for acceptance decision
1,00	RL	uv: conditional nb: rework, invoiced ab: rejects, invoiced rl: return to supplier nu: rework at our own cost* * no comment necessary

Heidelberger Druckmaschinen  
 Aktiengesellschaft

i.A. Helmut Braun

i.A. Christian Kellner

Chairman of the Supervisory Board: Standard; Dr. Mark Wössner, Company's registered office: Heidelberg, Commercial Register: Heidelberg HRB 4 Management Board: Bernhard Schreier (Chairman of the Management Board), Dirk Kallebe, Dr. Jürgen Rautert