




With increase print speed the energy efficiency increases



Energy values depends on used materials like substrates, inks, varnish, etc. and on external factors like the room temperature for example